

	Type	Hits	Search Text	DBs
1	BRS	0	circuit adj interrupter and timer and mis adj wiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	13	circuit adj interrupterand timer and mis adj wiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	9	GFCI and mis adj wiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	3	("6011398"   "6445196"   "6657435").PN.	USPAT
5	BRS	0	6734680.URPN.	USPAT
6	BRS	0	6734680.URPN.	USPAT
7	BRS	0	6734680.URPN.	USPAT
8	BRS	29	4,084,203	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	24	4,412,193	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
10	BRS	40	5,363,269	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	6	5,383,759	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	29	5,477,412	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	26	5,481,235	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
14	BRS	13	5,541,800	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	36	5,600,524	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
16	BRS	8	5,638,243	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	9	5,729,417	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	2218	361/42	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	0	circuit adj interrupter and timer and mis adj wiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
1	2004/10/31 14:49			0
2	2004/10/19 14:05			0
3	2004/10/13 14:22			0
4	2004/10/13 14:17			0
5	2004/10/13 14:19			0
6	2004/10/13 14:19			0
7	2004/10/13 14:19			0
8	2004/10/13 14:25			0
9	2004/10/13 14:26			0
10	2004/10/13 14:30			0
11	2004/10/13 14:31			0
12	2004/10/13 14:36			0
13	2004/10/13 14:37			0
14	2004/10/13 14:37			0
15	2004/10/13 14:39			0
16	2004/10/13 14:42			0
17	2004/10/13 14:49			0
18	2004/10/13 16:16			0
19	2004/10/19 14:48			0

	Type	Hits	Search Text	DBs
20	BRS	11	circuit adj interrupter and mis adj wiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	1	mis adj wiring near test	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	1	mis adj wiring and LM1851	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	9	mis adj wiring and GFCI	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	2	6,522,510	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	4	("4618907"   "5363269"   "5638243"   "6262871").PN.	USPAT
26	BRS	2	circuit adj interrupter and timer and (mis adj wiring or reverse adj wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	54	circuit adj interrupter and (mis adj wiring or reverse adj wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	26	circuit adj interrupter and (mis adj wiring or reverse adj wiring) same (trip tripping)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	23	6,246,558	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	12	("4034266"   "4595894"   "4719437"   "4802052"   "4851951"   "5223810"   "5224006"   "5594398"   "5600524"   "5805397"   "6040967"   "6246558").PN.	USPAT
31	BRS	12	("4034266"   "4595894"   "4719437"   "4802052"   "4851951"   "5223810"   "5224006"   "5594398"   "5600524"   "5805397"   "6040967"   "6246558").PN.	USPAT
32	BRS	12	("4034266"   "4595894"   "4719437"   "4802052"   "4851951"   "5223810"   "5224006"   "5594398"   "5600524"   "5805397"   "6040967"   "6246558").PN.	USPAT

	Time Stamp	Comments	Error Definition	Errors
20	2004/10/19 14:06			0
21	2004/10/19 14:37			0
22	2004/10/19 14:38			0
23	2004/10/19 14:45			0
24	2004/10/19 14:45			0
25	2004/10/19 14:45			0
26	2004/10/19 14:51			0
27	2004/10/19 14:51			0
28	2004/10/19 15:39			0
29	2004/10/19 15:04			0
30	2004/10/19 15:06			0
31	2004/10/19 15:06			0
32	2004/10/19 15:06			0

	Type	Hits	Search Text	DBs
33	BRS	11	("4034266"   "4595894"   "4719437"   "4802052"   "4851951"   "5223810"   "5224006"   "5594398"   "5600524"   "5805397"   "6040967").PN.	USPAT
34	BRS	11	("4034266"   "4595894"   "4719437"   "4802052"   "4851951"   "5223810"   "5224006"   "5594398"   "5600524"   "5805397"   "6040967").PN.	USPAT
35	BRS	42	5,363,269	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	3	5,363,269 and (mis adj wiring or reverse adj wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	88	("3932790"   "3936699"   "3976918"   "4024436"   "4045822"   "4063299"   "4345289"   "4368498"   "4412193"   "4538040"   "4567544"   "4568997"   "4574324"   "4595894"   "4618907"   "4709293"   "4742422"   "4802052"   "4831496"   "4872087"   "4939615"   "5166853"   "5184271"   "5202662"   "5223810"   "5270896"   "5270897"   "5334939"   "5363269"   "5402298"   "5406436"   "5418678"   "5477412"   "5510760"   "5541800"   "5546263"   "5568344"   "5583730"   "5594398"   "5600524"   "5638243"   "5654857"   "5661623"   "5680287"   "5684272"   "5701080"   "5706155"   "5715125"   "5729417"   "5747980"   "5757598"   "5768079"   "5781387"   "5786971"   "5793587"   "5801912"   "5825599"   "5841615"   "5864455"   "5894392"   "5917686"   "5936817"   "5946173"   "5963406"	USPAT

	Time Stamp	Comments	Error Definition	Errors
33	2004/10/19 15:06			0
34	2004/10/19 15:07			0
35	2004/10/19 15:44			0
36	2004/10/19 15:49			0
37	2004/10/19 15:45			0

	Type	Hits	Search Text	DBs
38	BRS	10	("4084203"   "4412193"   "5363269"   "5383759"   "5477412"   "5481235"   "5541800"   "5600524"   "5638243"   "5729417").PN.	USPAT
39	BRS	32	(trip tripping disconnect disconnecting) same (mis adj wiring or reverse adj wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	16	("4016489"   "4507698"   "4563719"   "4613934"   "4663571"   "4675576"   "4855860"   "4939427"   "5049787"   "5089752"   "5152218"   "5241443"   "5349273"   "5457360"   "5550437"   "5751523").PN.	USPAT
41	BRS	4	6040778.URPN.	USPAT
42	BRS	1103	361/45	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
43	BRS	756	high adj side adj switch	USPAT; US-PGPUB
44	BRS	153	high adj side adj switch and PNP	USPAT; US-PGPUB
45	BRS	37	high adj side adj switch and PNP and scr	USPAT; US-PGPUB
46	BRS	8	6,040,778	USPAT; US-PGPUB
47	BRS	10	5,847,909	USPAT; US-PGPUB
48	BRS	503	361/76	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
49	BRS	365	361/77	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
50	BRS	538	361/82	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
51	BRS	6	("3495096"   "3518491"   "3539868"   "3575616"   "3579043"   "3700919").PN.	USPAT

	Time Stamp	Comments	Error Definition	Errors
38	2004/10/19 15:47			0
39	2004/10/19 16:31			0
40	2004/10/19 16:22			0
41	2004/10/19 16:28			0
42	2004/10/19 16:32			0
43	2004/10/20 14:18			0
44	2004/10/20 14:18			0
45	2004/10/20 14:23			0
46	2004/10/20 14:41			0
47	2004/10/20 14:41			0
48	2004/10/20 16:16			0
49	2004/10/31 14:49			0
50	2004/10/31 15:42			0
51	2004/10/31 15:45			0